



# Hazardous Building Materials Register and Asbestos Management Plan



**Ashfield Council**

**Ashfield Aquatic Centre  
160 Elizabeth Street  
ASHFIELD NSW 2131**



**Survey Date: 28 September 2015**

**Report Date: 13 November 2015**

**Report Number: 9206.09.HMSR**



**GETEX PTY LIMITED**  
ABN 99 116 287 471

Suite 2.02, Level 2, Waterloo Business Park  
35 Waterloo Road, Macquarie Park NSW 2113  
Phone: (02) 98892488 Fax: (02) 98892499  
Email: [help@getex.com.au](mailto:help@getex.com.au) Web: [www.getex.com.au](http://www.getex.com.au)



Quality  
ISO 9001  
SAI GLOBAL

## Document Control

Revision Number	Revision Date	Document Number	Author	Author Signature	Reviewer	Reviewer Signature
Revision 0	13/11/2015	9206.09.HMSR	Peter Fox		Michael Tierney	



# Table of Contents

- 1. Executive Summary ..... 5
  - 1.1 Scope..... 5
  - 1.2 General Guidelines for Use ..... 6
- 2. Definitions ..... 7
- 3. Recommendations ..... 9
  - 3.1 Recommendations by Priority..... 9
    - 3.1.1 High Priority Recommendations (P1) ..... 9
    - 3.1.2 Medium Priority Recommendations (P2)..... 9
    - 3.1.3 Remedial Action.....10
    - 3.1.4 Low Priority Recommendations (P3 and P4).....10
  - 3.2 General Management Recommendations .....11
- 4. Statement of Limitations .....12
- 5. Methodology.....14
  - 5.1 Areas Not Accessed.....15
- 6. Controls.....16
- 7. Hazardous Building Materials Register (Refer to Assets Table Below) .....18
  - 7.1 How to Use the Hazardous Building Materials Register.....18
- 8. Asbestos Management Plan.....48
- 9. Hierarchy of Control .....48
- 10. Responsibilities .....49
  - 10.1 Responsibilities of Ashfield Council .....49
  - 10.2 Responsibilities of Maintenance Personnel & Tenants/Facility Managers.....49
  - 10.3 Responsibilities of Contractors & Emergency Personnel Working On-Site .....50
- 11. Consultation and Information.....51
- 12. Labelling.....52
- 13. Steps Required During Asbestos Related Works .....53
  - 13.1 General Site Set Up .....53
  - 13.2 General Requirements for Decontamination Works.....53
  - 13.3 Painting or Cleaning of Asbestos Cement Sheeting .....54
  - 13.4 Drilling into Asbestos Cement Sheeting or Backing Boards.....54
  - 13.5 Asbestos Air Monitoring & Clearance Inspection(s).....55
- 14. Emergency Response .....55
- 15. Review of the Asbestos Management Plan .....57

<b>Asset</b>	<b>Building Reference</b>	<b>Page Number</b>
1	Main Entrance Building	18
2	Pool Area	34
3	Indoor Pool	36
4	Caretakers Cottage/Plant Room	38

### **Appendix I Sample Register & Asbestos Sample Analysis Report**

# Hazardous Building Materials Register and Asbestos Management Plan

**Prepared For:** Ashfield Council

**Client Contact:** Ray McMaster

**Site:** Ashfield Aquatic Centre  
160 Elizabeth Street  
ASHFIELD NSW 2131

## 1. Executive Summary

### 1.1 Scope

Getex Pty Ltd (Getex™) was engaged by Ray McMaster of Ashfield Council to undertake a Hazardous Materials survey for the determination of the type, condition and extent of hazardous building materials that might be present at Ashfield Aquatic Centre, 160 Elizabeth Street, ASHFIELD NSW 2131.

The hazardous materials assessed included asbestos, lead in paint, lead in dust, Synthetic Mineral Fibre (SMF) and Polychlorinated Biphenyls (PCBs). The aim of the survey was to:

- Inspect all accessible areas of the site and identify any suspected hazardous building materials;
- Sample materials suspected of containing hazardous building materials;
- Compile a hazardous building materials register for the site;
- Provide advice regarding the ongoing management of hazardous building materials identified in the survey; and
- Prepare an asbestos management plan to provide advice regarding the ongoing management of asbestos materials identified in the survey.

The Getex Hazardous Building Materials Register and Asbestos Management Plan constitutes an Asbestos Register and an Asbestos Management Plan under the Safe Work Australia Code of Practice (How to Safely Remove Asbestos); and the Code of Practice (How to Manage and Control Asbestos in the Workplace) which are both approved under Section 274 of the Work Health and Safety Act 2011.

The site was investigated on 28 September 2015:

Investigator	Qualifications
Peter Fox	Consultant, BSc

## 1.2 General Guidelines for Use

The Hazardous building materials register is a list of building materials identified in the investigation that fall into one of these three categories:

- 1) The material was identified as containing Hazardous Materials;
- 2) The material was investigated and found not to contain Hazardous Materials, or
- 3) The material was considered to be of a type that could be confused with a hazardous material (e.g. fibre cement sheeting containing no asbestos).

Entries are presented within the register relating to each material that falls into one of the three categories listed by area along with an example photo of the material.

Please follow these general guidelines in the use of the register:

- 1) Ensure that a copy of the register is available on Site and may be viewed by contractors working in the area. Copies of the register are to be supplied to any tenants on request.
- 2) If work is being conducted in a particular area identify all hazardous items within the register and ensure the relevant controls are followed by workers or contractors if working in the vicinity of the material e.g. do not drill, cut grind or sand.
- 3) Remove all identified asbestos materials from Site prior to demolition or refurbishment activities that may disturb the materials.
- 4) Follow any other recommended controls relating to the relevant entry. Including make safe or remediation activities as specified for each item.
- 5) Ensure that the Asbestos Management Plan (Section 8) is read and understood by all parties listed in the Hierarchy of Control.

## 2. Definitions

### **Asbestos Related Works**

Any activities that may disturb asbestos containing materials in any way. Refer to Work Health and Safety Regulation 2011, Clause 419 for prohibitions and exceptions for asbestos related work.

### **Bonded Asbestos (Non Friable Asbestos)**

#### ***WH&S Regulation 2011***

Bonded asbestos material means any material (other than friable asbestos material) that contains asbestos.

#### ***WorkCover – Working with Asbestos, 2008***

Bonded asbestos material is any material that contains asbestos in a bonded matrix. It may consist of Portland cement or various resin/binders and cannot be crushed by hand when dry. Asbestos cement (AC) products and electrical metering boards in good condition are examples of bonded asbestos material.

#### ***Safe Work Australia Code of Practice (How to Safely Remove Asbestos) approved under Section 274 of the Work Health and Safety Act 2011.***

Means material containing asbestos that is not friable, including material containing asbestos fibres reinforced with a bonding compound.

### **Emergency Situation**

Uncontrolled disturbance of any asbestos containing material.

### **Friable Asbestos**

#### ***WH&S Regulation 2011***

Friable asbestos material means any material that contains asbestos and is in the form of a powder or can be crumbled, pulverised or reduced to powder by hand pressure when dry.

#### ***WorkCover – Working with Asbestos, 2008***

Friable asbestos material is any material that contains asbestos and is in the form of a powder or can be crumbled, pulverized or reduced to powder by hand pressure when dry. Sprayed limpet, millboard, pipe and boiler lagging are examples of friable asbestos.

Any asbestos cement products that have been subjected to weathering, or damaged by hail, fire or water blasting, are considered to be friable asbestos and an asbestos removal contractor with a WorkCover licence for friable asbestos is required for its removal.

***Safe Work Australia Code of Practice (How to Safely Remove Asbestos)  
approved under Section 274 of the Work Health and Safety Act 2011.***

Means material that is in a powder form or that can be crumbled, pulverised or reduced to a powder by hand pressure when dry, and contains asbestos.

**Permit To Work**

A document completed by contractors before commencing work acknowledging that they:

- Have read and understood the Hazardous Building Materials Register and Asbestos Management Plan (i.e. this report);
- Are aware of their legal obligations under the Work Health and Safety Act 2011;
- Have been provided the appropriate awareness training with regards to asbestos, and
- Reviewed safety controls with regard to the asbestos identified.

**Shadow Vacuuming Technique**

The use of a HEPA filtered vacuum with its nozzle placed close to an operating tool to capture dust generated by that tool.



### 3. Recommendations

#### 3.1 Recommendations by Priority

##### 3.1.1 High Priority Recommendations (P1)



P1

High priority items (Control Priorities P1) pose an unacceptable asbestos or hazardous material exposure health and safety risk under present conditions and require urgent remedial action.

P1 items are generally in poor to moderate condition and if asbestos are generally friable in nature. The risk to public health and safety posed by these items is considered to be extreme.

Some examples of P1 items are friable asbestos in dust and friable asbestos lagging debris.

Restrict access to areas containing P1 items immediately and erect signage at the entrances to the area. To ensure that the site is safe for continued use, these materials are to be remediated (as per controls recommended within the register) and a relevant Clearance Certificate obtained as per your obligations under the Work Health & Safety Regulations 2011 as soon as practicable.

If there is any significant delay in remediating these items, it is recommended that background monitoring be conducted in adjacent areas to assess the possible exposure pathways for the hazardous materials and the suitability of these areas for normal activities to proceed.

##### 3.1.2 Medium Priority Recommendations (P2)



P2

Medium priority items (Control Priorities P2) also pose an unacceptable asbestos or hazardous material exposure health and safety risk under present conditions and require remedial action as soon as practicable.

P2 items are generally in poor to moderate condition though generally non-friable in nature. The risk to public health and safety posed by these items is considered to be significant. Some examples of P2 items are asbestos cement debris and lead in dust greater than five times the guideline levels.

Limit access to these areas as much as is practicable immediately and erect signage at the entrances to the area. To ensure that the site is safe for continued use, these materials are to be remediated (as per controls recommended within the register) and an Asbestos Clearance Certificate obtained as per your obligations under the Work Health & Safety Regulations 2011 as soon as practicable.

### 3.1.3 Remedial Action



#### Remediated

Being familiar with the site, Getex can provide you with cost effective licensed asbestos remediation and an Asbestos or Hazardous Materials Clearance Certificate to certify that the site is safe for continued use.

Please contact Getex on (02) 9889 2488 for further information on how Getex can assist in ensuring your site is safe with respect to asbestos.

### 3.1.4 Low Priority Recommendations (P3 and P4)



#### P3

Low Priority items listed in the register (Control Priorities P3 and P4) may remain in place provided they are not disturbed e.g. do not drill, cut, grind or sand.

In some cases, these materials may require sealing of damaged sections or unsealed edges. Please refer to the control measures for the relevant item for more information on how these materials are to be managed.



#### P4

Some examples of P3 items are asbestos cement sheeting or asbestos vinyl tiles in good condition or with only minor damage. P4 items are by their placement restricted from any significant disturbance, for example, materials that are height restricted such as some asbestos eaves.

P3 and P4 items must be removed prior to any refurbishment or demolition activities within the relevant area.

### 3.2 General Management Recommendations

The labelling of all hazardous materials is recommended to warn of the dangers of disturbing these materials.

Getex recommends an annual reinspection of the identified Asbestos Containing Materials (ACM) remaining on-site as well as to monitor their condition as per the Code of Practice Code of Practice (How to Manage and Control Asbestos in the Workplace) approved under the Work Health and Safety Act 2011.

It is essential that prior to any demolition or refurbishment activities, the relevant ACM be removed by a suitably qualified licensed Class A or Class B asbestos removalist. If additional suspected ACM are encountered cease all demolition or refurbishment activities pending further investigation by a suitably qualified occupational hygienist such as Getex.

Where asbestos-containing materials are likely to be affected during renovations or maintenance work, then their removal by an accredited/licensed asbestos removalist should be considered prior to any work commencing, ensuring that the contractor has in place and can document their 'Asbestos Removal Control Plan' to safe guard against the release of asbestos fibres into the workplace.

All asbestos removal works must be done in accordance with the Safe Work Australia Code of Practice (How to Safely Remove Asbestos); and the Code of Practice (How to Manage and Control Asbestos in the Workplace).

Any material discovered that is suspected to be hazardous should be assumed to contain hazardous materials with relevant area(s) isolated until expert advice is obtained.

According to the Safe Work Australia Code of Practice (How to Safely Remove Asbestos); (p19) "Air monitoring is mandatory for all friable asbestos removal," and "Air monitoring should be considered where the asbestos removal work is being undertaken in or next to a public location".

Asbestos air monitoring should only be undertaken by an organisation NATA accredited for asbestos air monitoring and should be independent of the removal contractor.

Following removal of asbestos materials, the area must be assessed by a suitably qualified consultant and a clearance certificate issued subject to satisfactory assessment results.

Inspections of the identified hazardous materials should be undertaken every 5 years to ensure that the condition of the asbestos materials has not deteriorated and does not pose a risk to building occupants.

## 4. Statement of Limitations

Getex Pty Ltd and its staff members are professionally qualified and trained to achieve a suitable level of competency for the tasks undertaken.

Although all work is performed to a professional and diligent standard, the potential variance between the practical limitations of the scope of work undertaken, the cost of our services, all possible issues of concern, and any loss or damages which may be associated with our work are such that we cannot warrant that all issues of concern/asbestos materials have been identified. We therefore limit any potential liability associated with our work to the cost of our services.

All work conducted and/or reports/information produced by Getex Pty Ltd are prepared for a specific objective and within a specified scope of work as agreed between the Client and Getex Pty Ltd. As such this document is only for the use of the Client for the intended objective and may not be suitable for any other purpose. No parties other than the Client may use this document without first conferring with Getex Pty Ltd. Before passing this document onto a third party, the Client must inform the third party of any relevant information relating to this document. It is the responsibility of any party using this report to check to their satisfaction if this report is suitable for their intended use.

All information and/or report(s) prepared by Getex Pty Ltd should not be reproduced and/or presented/reviewed except in full.

Unless specifically mentioned, the inspection did not cover:

- Materials dumped, hidden, or otherwise placed in locations which one could not reasonably anticipate.
- Inaccessible/hidden locations, including wall cavities, under concrete slabs and lift wells.
- Materials other than standard building materials e.g. materials in special purpose facilities.
- Ground surface and underground areas.
- Mechanical, electrical or other items/materials not directly associated with the building structure.
- Materials other than asbestos as identification of a range of other possible hazardous substances can require specialised analysis/inspection techniques.

Where materials which may potentially contain asbestos are identified, these are reported to the best of the consultant's ability. Analysis/testing of materials is generally not included and there is no guarantee that all such materials have been identified.

The investigation conducted was limited in scope. As such, Getex Pty Ltd cannot guarantee that any or all asbestos materials/issues of concern, if present, have been identified as the practical restrictions of the program involved the inspection/review of a limited number of locations/materials which may or may not have identified/intercepted all asbestos materials if present. Furthermore, the distribution of dust, asbestos materials and/or other contaminants may vary with location and there can be no guarantee that a particular sample/location is typical of an extended area.

Settled dusts are known to exist in variety of locations in the general environment and possibly contain a range of substances which may be hazardous at varying levels, particularly if the dust is in the vicinity of hazardous materials such as asbestos containing materials or paint containing lead. Furthermore dusts present may originate from a variety of known and unknown complex sources (such as environmental/atmospheric) that are not related to the presence of bulk hazardous building materials e.g. combustions emissions from automobiles or industry. Due to the above mentioned potential complex sources of dust which may not be identifiable, settled dust is not sampled or commented on except where otherwise stated.

## 5. Methodology

All accessible areas of the buildings on Site were thoroughly inspected for the determination of the type, condition and extent of any hazardous building materials including asbestos, lead in paint, lead in dust, Synthetic Mineral Fibre (SMF) and Polychlorinated Biphenyls (PCBs) that might be present.

Where visual examination of a material proved to be inconclusive, samples were collected for laboratory analysis. Samples were collected by non-destructive and non-intrusive techniques where available.

Determination of materials containing or potentially containing asbestos or synthetic mineral fibre was based on a visual examination and/or sampling and analysis.

All asbestos samples were analysed by Getex's NATA accredited Laboratory. Asbestos samples were analysed for the qualitative identification of asbestos type fibres in bulk using Polarised Light Microscopy and Dispersion Staining Techniques.

In accordance with Appendix A of Australian Standard AS 4361.2-1998, areas of paint were spot tested for the presence of Lead by wiping exposed areas with a cotton swab soaked with 5% w/v aqueous sodium sulfide solution. A positive result is indicated by a darkening of the test area and a Lead content of greater than 1%.

All paint and dust samples were analysed by a NATA accredited organisation.

Paint samples were analysed for lead content by digestion of paint chips with aqua regia followed by determination of lead in the digest using Inductively Coupled Plasma (ICP) in accordance with Appendix A – Australian Standard AS 4361.2-1998.

Moistened wipes were used to collect surface dust from a known area on the upper side of the ceiling in accordance with Appendix C – Australian Standard AS 4361.2 1998. The dust samples were analysed by sample digestion with Nitric Acid and Hydrogen Peroxide followed by determination of lead in the digest using ICP in accordance with Appendix C – AS 4361.2-1998.

After the completion of the hazardous materials survey, a register was prepared outlining occurrences of hazardous materials in each asset, the condition of the hazardous material the treatment option required and the priority of treatment. The Hazardous Materials Register details the location, description, type, condition, and risk priority of presumed or identified hazardous materials.

## 5.1 Areas Not Accessed

All reasonable effort was made to investigate the entire property. Where this is not possible due to restrictions caused by construction or safety, an entry is made within the register noting that the area has not been inspected and the reason for this. Such areas include, but are not limited to:

- Height restricted areas;
- Gas, electrical, chemical or pressurised service lines;
- Within service shafts, ducts and wall cavities;
- Areas obstructed by installed equipment; and
- Locked areas to which no key is available at the time of inspection.

Further investigation of these areas is required if refurbishment or demolition activities within these areas are to proceed.

## 6. Controls


- 1) This Hazardous Building Materials Register and Asbestos Management Plan is to remain on site in a readily accessible location for perusal by interested parties at any time. It is of particular importance that this Hazardous Building Materials Register and Asbestos Management Plan be updated following the removal and disposal of any hazardous building materials or any changes in condition. If works are to involve items of suspect material not covered within the scope of this report it is recommended that confirmation of the material as containing/not containing hazardous materials takes place prior to refurbishment or demolition works.
- 2) All building occupants, visitors to the site, and in particular, service maintenance personnel are to be advised of hazardous building materials management procedures in accordance with the standards and guidelines.
- 3) Prior to any works being undertaken on the site it is important that the Hazardous Building Materials Register and Asbestos Management Plan is reviewed. It is essential that all persons / tradespeople who are required to work on the building be notified about the presence of the hazardous building materials in the identified areas and procedures required to be followed.
- 4) Regular inspections of the identified hazardous building materials is to be undertaken (a minimum of every 5 years) to ensure that the condition of the hazardous materials has not deteriorated and does not pose a risk to building occupants.
- 5) Guidance noted in: the Safe Work Australia Code of Practice (How to Safely Remove Asbestos); and the Code of Practice (How to Manage and Control Asbestos in the Workplace); AS 4361.2 1998 Guide to Lead Paint Management Part 2: Residential and Commercial Buildings; Polychlorinated Biphenyls Management Plan ANZECC (Revised Edition April 2003); National Code of Practice for the Safe Use of Synthetic Mineral Fibres [NOHSC:2006(1990)], and the National Code of Practice for the Control of Inorganic Lead at Work Lead in Paint [NOHSC:2015(1994)] should be followed for all hazardous building materials.
- 6) Any material discovered that is suspected to be a hazardous building material should be assumed to contain hazardous materials with relevant area(s) isolated until expert advice is obtained.
- 7) All hazardous materials removal/treatment works or other works which may disturb hazardous containing materials should follow an appropriate detailed work specific control strategy setting out the procedures and precautions that are to be taken to ensure health and safety with respect to hazardous exposures. The control strategy should include Safe Work Method Statements, a Hazardous Materials Work Plan and Management Plans. Prior to undertaking such works it is recommended that the advice of a suitably qualified occupational hygienist, such as Getex Pty Ltd, be sought.
- 8) If any hazardous building materials are to remain in place an appropriate ongoing hazardous materials management plan is to be prepared and implemented to ensure that the risks associated with these materials are controlled and maintained at an acceptable level.



- 9) All hazardous building removal/treatment activities are to be undertaken by an experienced and licensed removal contractor.
- 10) According to the Safe Work Australia Code of Practice (How to Safely Remove Asbestos); (p19) "Air monitoring is mandatory for all friable asbestos removal," and "Air monitoring should be considered where the asbestos removal work is being undertaken in or next to a public location."
- 11) Asbestos/SMF and Lead air monitoring is to be undertaken by an organisation NATA accredited for air monitoring and who is independent of the removal contractor.
- 12) Following removal of asbestos containing building materials, lead containing paints and lead dust, the area is to be assessed by a suitably qualified consultant, such as Getex Pty Ltd, and an asbestos or lead clearance certificate issued subject to satisfactory assessment results.

## 7. Hazardous Building Materials Register

### 7.1 How to Use the Hazardous Building Materials Register

ID	Location	Material Type	Analysis Result	Sample No.	Extent	Condition	Friability	Disturbance Potential	Re-inspect Date	Control Priority	Control Measures	Removal Date	Removed	Photos
Exterior														
2	Eaves Southern extension	Asbestos Cement Sheeting	Positive <i>Chrysotile Asbestos Detected</i>	9038/AS04B	~40m <sup>2</sup>	Good	Non-Friable	Low	Low	May 2018	<div style="background-color: yellow; padding: 5px;">                     Material in good condition, do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.                 </div> P3	Date: _____ Removed by: _____ Report: _____	 <p>Photo 12</p> <p>Asbestos cement eaves</p>	
Comments: All eaves throughout the dwelling are assessed to contain asbestos.														

Example Only

Easy to understand colour coding of materials according to **priority.**

Your notes regarding removal of materials

Example Photo of the material

Area Reference

Site Unique Entry ID Number

Location Description

Material Type

Analysis Result

Approx. Extent

Information relating to condition and risk status of the item

Re-inspection Date

Priority Ranking

Recommended Controls

Ensure that a copy of the register is available on Site and may be viewed by contractors working in the area. Copies of the register are to be supplied to any tenants on request. If work is being conducted in a particular area identify all hazardous items within the register and ensure the relevant controls are followed by workers or contractors if working in the vicinity of the material e.g. do not drill, cut grind or sand.

# HAZARDOUS BUILDING MATERIALS REGISTER

Prepared by Getex



## Main Entrance Building






Site Address: Ashfield Aquatic Centre,  
160 Elizabeth Street  
ASHFIELD NSW 2131




Investigated: 28 September 2015  
Consultant: Peter Fox BSc










Asset Photo






ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Exterior</b>														
1	Door frames and window frames Throughout - White paint	Paint	9206.09/LP01	Negative Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 1 
														White Door Frame Paint
2	Eastern side Wall and carport - Upper panels	Fibre Cement Sheeting	9206.09/AS01	Negative No Asbestos Detected	-	-	-	-	-	-	-	-	-	Photo 2 
														Fibre Cement Sheeting

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Exterior (Cont..)</b>														
3	<b>Eaves</b> Panel inserts between concrete blocks	Asbestos Cement Sheeting	Previously sampled by NAA 41310-(310805)-16	<b>Positive</b>  <i>Asbestos Detected</i>	~50m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 <b>P3</b>	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: _____ Removed by: _____ Report: _____	<b>Photo 3</b> 
														<i>Asbestos Cement Sheeting</i>
4	<b>Eaves</b> Panel inserts between concrete blocks - Pointing material	Pointing Material	Previously sampled by NAA 41310-(310805)-17	<b>Positive</b>  <i>Asbestos Detected</i>	~50m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 <b>P3</b>	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: _____ Removed by: _____ Report: _____	<b>Photo 4</b> 
														<i>Pointing Material</i>
5	<b>Kiosk</b> Southern Side - Awning	Fibre Cement Sheeting	Same as Sample 9206.09/AS02	<b>Negative</b> No Asbestos Detected (Assessed to be Similar to Sample 9206.09/AS02 )	-	-	-	-	-	-	-	-	-	<b>Photo 5</b> 
														<i>Fibre Cement Sheeting</i>






ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Exterior (Cont..)</b>														
6	<b>Male Staff Change Room</b> Southern entrance door - Blue paint	Paint	Same as Sample 9206.09/LP02	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	<p>Photo 6</p> 
														<i>Blue Door Paint</i>
7	<b>Non timber panel doors</b> Throughout - Blue paint	Paint	9206.09/LPST13	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	<p>Photo 7</p> 
Comments: Building built circa 2000.														<i>Blue Door Paint</i>
8	<b>Northern Side</b> Kiosk carport - Eaves	Fibre Cement Sheeting	Previously sampled by NAA 41310-(310805)-15	<b>Negative</b> No Asbestos Detected	-	-	-	-	-	-	-	-	-	<p>Photo 8</p> 
														<i>Fibre Cement Sheeting</i>





ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Exterior (Cont..)</b>														
9	<b>Northern Side</b> Kiosk carport - Eaves and ceiling - White paint	Paint	9206.09/LPST18	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	<b>Photo 9</b> 
													<b>White Eaves Paint</b>	
10	<b>Southern side</b> Door adjacent west of western clock - Blue paint and multiple undercoats	Paint	9206.09/LP02	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	<b>Photo 10</b> 
													<b>Blue Door Paint</b>	
11	<b>Southern wall</b> Western end - Electrical meter box - Electrical backing board	Electrical Backing Board	-	<b>Assumed Positive</b> <i>Assumed to Contain Asbestos (Visually Assessed)</i>	~0.25m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 <b>P3</b>	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment, demolition works or any electrical works that require drilling.	Date: ____/____/____ Removed by: _____ Report: _____	<b>Photo 11</b> 
Comments: Not sampled due to live electricity. Isolate using a licensed electrician and conduct investigation to confirm status.													<b>Electrical Backing Board</b>	



ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Exterior (Cont..)</b>														
12	<b>Walls</b> Throughout - Blue paint trim	Paint	9206.09/LPST02	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 12 
														Blue Paint Trim
13	<b>Walls</b> Throughout - White paint	Paint	9206.09/LPST01	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 13 
														White Wall Paint
<b>Interior</b>														
14	<b>Community Room</b> Bathroom - Non solid walls	Fibre Cement Sheeting	Same as Sample 9206.09/AS02	<b>Negative</b> No Asbestos Detected (Assessed to be Similar to Sample 9206.09/AS02 )	-	-	-	-	-	-	-	-	-	Photo 14 
														Fibre Cement Sheeting




ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Interior (Cont..)</b>														
15	<b>Female Change Rooms</b> Western walls - Non solid walls	Fibre Cement Sheeting	Same as Sample 9206.09/ AS02	<b>Negative</b> No Asbestos Detected (Assessed to be Similar to Sample 9206.09/AS02 )	-	-	-	-	-	-	-	-	-	<b>Photo 15</b> 
														<b>Fibre Cement Sheetting</b>
16	<b>First Aid Room</b> Light & Dark Green vinyl floor tiles	Vinyl Tile	Previously sampled by NAA Same as 41310- (310805)- 10 & 41310- (310805)- 11	<b>Positive</b>  <i>Asbestos Detected</i>	-	Good/ Minor Damage	Non- Friable	Low	Low	Sep 2018	 <b>P3</b>	Label, seal any damaged areas and maintain in good condition. Do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: ____/____/____ Removed by: _____ Report: _____	<b>Photo 16</b> 
														<b>Vinyl Tile</b>
17	<b>First Aid Room</b> Walls - Adjacent change room - Walls - Beige paint	Paint	9206.09/ LPST06	<b>Positive</b>  <i>Lead in Paint &gt;1.0%</i>	~24m <sup>2</sup>	Unsealed, Good Condition	-	Low	Low	Sep 2018	 <b>P3</b>	Lead in paint level is >1.0%. Confirm percentage lead content by lab analysis. Manage in accordance with AS 4361.2 1998 Guide to Lead Paint Management Part 2: Residential and Commercial Buildings.	Date: ____/____/____ Removed by: _____ Report: _____	<b>Photo 17</b> 
														<b>Beige Wall Paint</b>









ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Interior (Cont..)</b>														
18	<b>First Aid Room</b> Walls - Blue paint and undercoats	Paint	9206.09/LP04	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	
														<b>Blue Wall Paint</b>
19	<b>Fluorescent Lights</b> Throughout	Fluorescent Lights	-	<b>Positive</b> May Contain PCBs (Visually Assessed)	> 50 Fittings	Good Condition, No Leaking Observed	-	Low	Low	Sep 2018	 P3	Mat contains PCBs. The material may remain in place provided it is not disturbed. Ensure that capacitors are managed in accordance with the Polychlorinated Biphenyls Management Plan ANZECC (Revised Edition April 2003).	Date: ___/___/___ Removed by: _____ Report: _____	
Comments: Not assessed due to live electricity. Test while isolated and tagged by a licensed electrician.														<b>Fluorescent Lights</b>
20	<b>Main entrance</b> Ceiling throughout - Vermiculite (inaccessible)	Vermiculite	-	<b>Assumed Positive</b> Assumed to Contain Asbestos (Visually Assessed)	~120m <sup>2</sup>	Good	Friable	Low	Low	Sep 2018	 P3	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A asbestos removalist under friable conditions as soon as practicable and prior to any refurbishment, demolition works.	Date: ___/___/___ Removed by: _____ Report: _____	
														<b>Vermiculite</b>




ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Interior (Cont..)</b>														
21	<b>Male Staff Change Room</b> Walls - Yellow paint	Paint	9206.09/LPST07	<b>Positive</b> <i>Lead in Paint &gt;1.0%</i>	~24m <sup>2</sup>	Unsealed, Good Condition	-	Low	Low	Sep 2018	 P3	Lead in paint level is >1.0%. Confirm percentage lead content by lab analysis. Manage in accordance with AS 4361.2 1998 Guide to Lead Paint Management Part 2: Residential and Commercial Buildings.	Date: _____ Removed by: _____ Report: _____	 <b>Photo 21</b>
														<b>Yellow Wall Paint</b>
22	<b>Men's change room</b> Ceiling - Skylight barge board (inaccessible)	Asbestos Cement Sheeting	-	<b>Assumed Positive</b> <i>Assumed to Contain Asbestos (Visually Assessed)</i>	~1m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 P3	Maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: _____ Removed by: _____ Report: _____	 <b>Photo 22</b>
														<b>Asbestos Cement Sheeting</b>
23	<b>Men's Change Room</b> Eastern non solid walls	Fibre Cement Sheeting	9206.09/AS02	<b>Negative</b> No Asbestos Detected	-	-	-	-	-	-	-	-	-	





ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Interior (Cont..)</b>														
24	<b>Men's Change Room</b> Infill/service panel adjacent west of entrance	Fibre Cement Sheeting	Same as Sample 9206.09/AS02	<b>Negative</b> No Asbestos Detected (Assessed to be Similar to Sample 9206.09/AS02 )	-	-	-	-	-	-	-	-	-	
25	<b>Room south of Club Room</b> Eastern wall	Masonite	-	<b>Negative</b> No Asbestos Detected (Visually Assessed)	-	-	-	-	-	-	-	-	-	<a href="#">Photo 23</a> 
<i>Masonite</i>														
26	<b>Walls throughout</b> White paint	Paint	9206.09/LPST03	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	<a href="#">Photo 24</a> 
<i>White Wall Paint</i>														

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Interior (Cont..)</b>														
27	<b>Women's change room</b> Ceiling - Skylight barge board (inaccessible)	Asbestos Cement Sheeting	-	<b>Assumed Positive</b> <i>Assumed to Contain Asbestos (Visually Assessed)</i>	~1m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 P3	Maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: _____ Removed by: _____ Report: _____	
<b>Kiosk - Interior</b>														
28	<b>Kiosk</b> Kitchen - Electrical backing board (inaccessible)	Electrical Backing Board	-	<b>Assumed Positive</b> <i>Assumed to Contain Asbestos (Visually Assessed)</i>	~1m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 P3	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment, demolition works or any electrical works that require drilling.	Date: _____ Removed by: _____ Report: _____	
Comments: Not located during 2015 re-inspection.														
29	<b>Kitchen area</b> Walls - White paint	Paint	9206.09/LPST08	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	
														<b>White Wall Paint</b>






ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Kiosk - Interior (Cont..)</b>														
30	Shop area Walls - Maroon paint	Paint	9206.09/ LPST09	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 26 
														Maroon Wall Paint
31	Shop area Walls - Maroon paint	Paint	9206.09/ LPST09	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 26 
														Maroon Wall Paint
<b>Office South of Entrance - Interior</b>														
32	Door and door frames Blue paint	Paint	9206.09/ LPST05	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 27 
														Blue Door Paint

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Office South of Entrance - Interior (Cont..)</b>														
33	Northern section of ceiling	Masonite	-	<b>Negative</b> No Asbestos Detected (Visually Assessed)	-	-	-	-	-	-	-	-	-	Photo 28 
														Masonite
34	<b>North-western room</b> Eastern wall - Brown vinyl floor tiles and adhesive	Vinyl Tile & Adhesive	9206.09/AS03	<b>Negative</b> No Asbestos Detected	-	-	-	-	-	-	-	-	-	Photo 29 
														Vinyl Tile & Adhesive
35	<b>North-western room</b> Eastern wall - Electrical backing board	Electrical Backing Board	-	<b>Negative</b> No Asbestos Detected (Visually Assessed)	-	-	-	-	-	-	-	-	-	Photo 30 
														Electrical Backing Board

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Office South of Entrance - Interior (Cont..)</b>														
36	Walls throughout Blue paint	Paint	9206.09/ LPST04	<b>Negative</b>  Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 31 
														<i>Blue Wall Paint</i>
37	Yellow vinyl floor tiles	Vinyl Tile	Previously sampled by NAA 41310-(310805)-13	<b>Negative</b>  No Asbestos Detected	-	-	-	-	-	-	-	-	-	
Comments: Not located during 2015 re-inspection presumed to be removed.														
<b>Office West of entrance - Interior</b>														
38	Floor Dark green vinyl floor tiles	Vinyl Tile	Previously sampled by NAA 41310-(310805)-10	<b>Positive</b>  <i>Asbestos Detected</i>	~2m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 P3	Label and maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: ____/____/____ Removed by: _____ Report: _____	Photo 32 
Comments: Previously listed as Kitchen in NAA survey, now converted to an office.														<i>Vinyl Tile</i>

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Office West of entrance - Interior (Cont..)</b>														
39	Floor Grey vinyl tiles	Vinyl Tile	Previously sampled by NAA 41310-(310805)-12	<b>Negative</b> No Asbestos Detected	-	-	-	-	-	-	-	-	-	
Comments: Previously listed as Kitchen in NAA survey, now converted to an office.														<a href="#">Vinyl Tile</a>
40	Floor Light green vinyl tiles	Vinyl Tile	Previously sampled by NAA 41310-(310805)-10	<b>Positive</b> Asbestos Detected	~10m <sup>2</sup>	Good/ Minor Damage	Non-Friable	Low	Low	Sep 2018	 P3	Label, seal any damaged areas and maintain in good condition. Do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: ____/____/____ Removed by: _____ Report: _____	
Comments: Previously listed as Kitchen in NAA survey, now converted to an office.														<a href="#">Vinyl Tile</a>
41	Interior dividing wall Eastern side	Masonite	-	<b>Negative</b> No Asbestos Detected (Visually Assessed)	-	-	-	-	-	-	-	-	-	
														<a href="#">Masonite</a>



ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Office West of entrance - Interior (Cont..)</b>														
42	Interior dividing wall Western side	Asbestos Cement Sheeting	Previously sampled by NAA 41310-(310805)-09	<b>Positive</b>  <i>Asbestos Detected</i>	~6m <sup>2</sup>	Good/ Minor Damage	Non-Friable	Low	Low	Sep 2018	 P3	Label, seal any damaged areas and maintain in good condition. Do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: _____ Removed by: _____ Report: _____	 Photo 36
Comments: Previously listed as Kitchen in NAA survey, now converted to an office.														<i>Asbestos Cement Sheeting</i>
43	Walls throughout Cream wall paint and undercoats	Paint	9206.09/LP03	<b>Negative</b>  Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	 Photo 37
														<i>Cream Wall Paint</i>
44	Western wall Southern electrical distribution board - Electrical backing board (inaccessible)	Electrical Backing Board	-	<b>Assumed Positive</b>  <i>Assumed to Contain Asbestos (Visually Assessed)</i>	~2m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 P3	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment, demolition works or any electrical works that require drilling.	Date: _____ Removed by: _____ Report: _____	 Photo 38
Comments: Not sampled due to live electricity. Isolate using a licensed electrician and conduct investigation to confirm status.														<i>Electrical Backing Board</i>

# HAZARDOUS BUILDING MATERIALS REGISTER

Prepared by Getex



## Pool Area




**Site Address:** Ashfield Aquatic Centre,  
160 Elizabeth Street  
ASHFIELD NSW 2131

**Investigated:** 28 September 2015  
**Consultant:** Peter Fox BSc



Asset Photo

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Exterior</b>														
45	Outdoor pools Blue paint trim	Paint	9206.09/ LPST11	Negative Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 39 
														Blue Paint Trim
46	Walls Throughout - Purple paint	Paint	9206.09/ LPST10	Negative Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 40 
														Purple Paint

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Grandstands</b>														
47	<b>Walls and floor</b> White paint and grey undercoat	Paint	9206.09/ LPST12	<b>Negative</b>  Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	 <b>Photo 41</b>
														<b>White Wall Paint</b>
48	<b>Western Grandstand</b> Storage under southern end - Electrical backing board (inaccessible)	Electrical Backing Board	-	<b>Assumed Positive</b>  <i>Assumed to Contain Asbestos (Visually Assessed)</i>	~0.25m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 <b>P3</b>	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment, demolition works or any electrical works that require drilling.	Date: ____/____/____ Removed by: _____ Report: _____	 <b>Photo 42</b>
														<b>Electrical Backing Board</b>

# HAZARDOUS BUILDING MATERIALS REGISTER

Prepared by Getex




## Indoor Pool

Site Address: Ashfield Aquatic Centre,  
160 Elizabeth Street  
ASHFIELD NSW 2131

Investigated: 28 September 2015  
Consultant: Peter Fox BSc



Asset Photo

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Exterior/Interior</b>														
49	Throughout	Fibre Cement Sheeting	-	Negative No Asbestos Detected (Visually Assessed)	-	-	-	-	-	-	-	-	-	Photo 43 
														Various
<b>Interior</b>														
50	Ceiling Insulation	Synthetic Mineral Fibre	-	Positive Synthetic Mineral Fibres Detected (Visually Assessed)	~90m <sup>2</sup>	Good	-	Low	Low	Sep 2018	 P3	Material may remain in place provided it is not disturbed. e.g. do not drill, cut, grind or sand. Manage in accordance with the National Code of Practice for the Safe Use of Synthetic Mineral Fibres [NOHSC:2006(1990)].	Date: _____ Removed by: _____ Report: _____	Photo 44 
														Synthetic Mineral Fibre

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Interior (Cont..)</b>														
51	Florescent lights Throughout	Fluorescent Lights	-	<b>Negative</b> No PCBs Detected (Visually Assessed)	-	-	-	-	-	-	-	-	-	
Comments: Building built circa 2000.														

# HAZARDOUS BUILDING MATERIALS REGISTER

Prepared by Getex

## Caretakers Cottage/Plant Room





Site Address: Ashfield Aquatic Centre,  
160 Elizabeth Street  
ASHFIELD NSW 2131





Investigated: 28 September 2015  
Consultant: Peter Fox BSc









Asset Photo





ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Cottage - Exterior</b>														
52	Eaves Throughout	Asbestos Cement Sheeting	-	<b>Positive</b> <i>Asbestos Detected (Visually Assessed)</i>	~50m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	P3	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: _____ Removed by: _____ Report: _____	 Photo 45
														<i>Asbestos Cement Sheeting</i>
53	Metal windows Throughout - Mastic	Mastic	9206.09/AS08	<b>Negative</b> No Asbestos Detected	-	-	-	-	-	-	-	-	-	 Photo 46
														<i>Mastic</i>





ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Cottage - Exterior (Cont..)</b>														
54	Northern entrance Panel adjacent east	Masonite	-	Negative No Asbestos Detected (Visually Assessed)	-	-	-	-	-	-	-	-	-	Photo 47 
														Masonite
55	Southern exterior entrance Exterior eastern panels	Asbestos Cement Sheeting	Previously sampled by NAA 41310-(310805)-14	Positive Asbestos Detected	~10m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 P3	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: _____ Removed by: _____ Report: _____	Photo 48 
														Asbestos Cement Sheeting
56	Window and door frames Throughout - White paint	Paint	Same as Sample 9206.09/LP01	Negative Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 49 
														White Window Paint




ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Cottage - Interior</b>														
57	<b>Door Frames and skirting boards</b> Throughout - Cream paint	Paint	Same as Sample 9206.09/LP06	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 50 
														<i>Cream Door Frame Paint</i>
58	<b>Kitchen</b> Floor - Green vinyl tiles under seamless vinyl	Vinyl Tile	9206.09/AS05	<b>Negative</b> No Asbestos Detected	-	-	-	-	-	-	-	-	-	Photo 51 
														<i>Vinyl Tile</i>
59	<b>Kitchen</b> Floor - Seamless vinyl	Seamless Vinyl	9206.09/AS04	<b>Positive</b> <i>Chrysotile Asbestos Detected</i>	~15m <sup>2</sup>	Moderate	Non-Friable	Medium	Medium	Sep 2016	 <b>P2</b>	Label, restrict access and remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: ___/___/___ Removed by: _____ Report: _____	Photo 52 
														<i>Seamless Vinyl</i>












ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Cottage - Interior (Cont..)</b>														
60	<b>Kitchen</b> Floor - Seamless vinyl debris	Seamless Vinyl Debris	Same as Sample 9206.09/AS04	<b>Positive</b> <i>Asbestos Detected</i>	~15m <sup>2</sup>	Poor	Non-Friable	Low	Medium	Sep 2016	 P2	Label, Restrict access and remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: _____ Removed by: _____ Report: _____	 <b>Photo 53</b>
														<i>Seamless Vinyl Debris</i>
61	<b>Kitchen</b> Southern wall - Electrical Backing Board (inaccessible)	Electrical Backing Board	-	<b>Assumed Positive</b> <i>Assumed to Contain Asbestos (Visually Assessed)</i>	~0.25m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 P3	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment, demolition works or any electrical works that require drilling.	Date: _____ Removed by: _____ Report: _____	 <b>Photo 54</b>
														<i>Electrical Backing Board</i>
62	<b>Laundry</b> Ceiling	Asbestos Cement Sheeting	-	<b>Positive</b> <i>Asbestos Detected (Visually Assessed)</i>	~12m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 P3	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: _____ Removed by: _____ Report: _____	 <b>Photo 55</b>
														<i>Asbestos Cement Sheeting</i>



ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Cottage - Interior (Cont..)</b>														
63	<b>Laundry</b> Ceiling and upper timber trim - Cream paint	Paint	9206.09/LP06	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 56 
														<i>Cream Timber Trim Paint</i>
64	<b>Laundry</b> Walls - Yellow paint	Paint	9206.09/LPST15	<b>Positive</b> Lead in Paint >1.0%	~20m <sup>2</sup>	Unsealed, Minor Flaking Paint	-	Low	Low	Sep 2018	 P3	Lead in paint level is >1.0%. Confirm percentage lead content by lab analysis. Manage in accordance with AS 4361.2 1998 Guide to Lead Paint Management Part 2: Residential and Commercial Buildings.	Date: _____ Removed by: _____ Report: _____	Photo 57 
														<i>Yellow Wall Paint</i>
65	<b>Metal window frames</b> Throughout - Mastic	Mastic	9206.09/AS06	<b>Negative</b> No Asbestos Detected	-	-	-	-	-	-	-	-	-	Photo 58 
														<i>Mastic</i>

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Cottage - Interior (Cont..)</b>														
66	<b>Southern entrance hall</b> Ceiling	Asbestos Cement Sheeting	-	<b>Positive</b> <i>Asbestos Detected (Visually Assessed)</i>	~4.5m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 <b>P3</b>	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: ____/____/____ Removed by: _____ Report: _____	 <b>Photo 59</b>
														<i>Asbestos Cement Sheeting</i>
67	<b>Southern entrance hall</b> Eastern wall	Fibre Cement Sheeting	9206.09/AS07	<b>Negative</b> No Asbestos Detected	-	-	-	-	-	-	-	-	-	 <b>Photo 60</b>
														<i>Fibre Cement Sheeting</i>
68	<b>Southern entrance hall</b> Southern wall	Masonite	-	<b>Negative</b> No Asbestos Detected (Visually Assessed)	-	-	-	-	-	-	-	-	-	 <b>Photo 61</b>
														<i>Masonite</i>

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Cottage - Interior (Cont..)</b>														
69	Walls throughout Beige paint	Paint	9206.09/ LP05	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 62 
													Beige Wall Paint	
70	Walls throughout Green paint	Paint	9206.09/ LPST14	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	Photo 63 
													Green Wall Paint	
<b>Plant Room - Interior</b>														
71	Below pool area Conduit pipe - Fibre cement moulded pipe	Asbestos Cement Sheeting	-	<b>Assumed Positive</b>  <i>Assumed to Contain Asbestos (Visually Assessed)</i>	~20m <sup>2</sup>	Good	Non- Friable	Low	Low	Sep 2018	 <b>P3</b>	Maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment or demolition works.	Date: ____/____/____ Removed by: _____ Report: _____	
Comments: Listed in NAA survey. Not located at time of re-inspection presumed to still be present (potentially in the confined space).														

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Plant Room - Interior (Cont..)</b>														
72	<b>Ceiling and upper beams</b>  White paint	Paint	9206.09/ LPST16	<b>Negative</b>  Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	<b>Photo 64</b> 
														<b>White Beam Paint</b>
73	<b>Fluorescent Lights</b>  Throughout	Fluorescent Lights	-	<b>Positive</b>  <i>May Contain PCBs Detected (Visually Assessed)</i>	> 5 Fittings	Good Condition, No Leaking Observed	-	Low	Low	Sep 2018	 P3	May contains PCBs. The material may remain in place provided it is not disturbed. Ensure that capacitors are managed in accordance with the Polychlorinated Biphenyls Management Plan ANZECC (Revised Edition April 2003).	Date: _____ Removed by: _____ Report: _____	<b>Photo 65</b> 
Comments: Not assessed due to live electricity. Test while isolated and tagged by a licensed electrician.														<b>Fluorescent Lights</b>
74	<b>Main soil valve</b>  Gasket	Gasket	9206.09/ AS09	<b>Negative</b>  No Asbestos Detected	-	-	-	-	-	-	-	-	-	<b>Photo 66</b> 
														<b>Gasket</b>

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Plant Room - Interior (Cont..)</b>														
75	<b>Northern wall</b> Three electrical backing boards (inaccessible)	Electrical Backing Board	-	<b>Assumed Positive</b> <i>Assumed to Contain Asbestos (Visually Assessed)</i>	~2m <sup>2</sup>	Good	Non-Friable	Low	Low	Sep 2018	 P3	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment, demolition works or any electrical works that require drilling.	Date: _____ Removed by: _____ Report: _____	 <b>Photo 67</b>
														<b>Electrical Backing Board</b>
76	<b>Wall adjacent to northern entrance</b> Electrical backing board (inaccessible)	Electrical Backing Board	-	<b>Assumed Positive</b> <i>Assumed to Contain Asbestos (Visually Assessed)</i>	-	Good	Non-Friable	Low	Low	Sep 2018	 P3	Label, maintain in good condition, and do not disturb (e.g. do not drill, cut grind or sand). Remove by a licensed Class A or Class B asbestos removalist as soon as practicable and prior to any refurbishment, demolition works or any electrical works that require drilling.	Date: _____ Removed by: _____ Report: _____	 <b>Photo 68</b>
														<b>Electrical Backing Board</b>
77	<b>Walls throughout</b> Light green wall paint	Paint	9206.09/LP07	<b>Negative</b> Lead in Paint <1.0%	-	-	-	-	-	-	-	-	-	 <b>Photo 69</b>
														<b>Light Green Wall Paint</b>

ID	Location	Material Type	Sample No.	Analysis Result	Extent	Condition	Friability	Disturbance Potential	Risk Status	Re-inspect Date	Control Priority	Control Recommendation	Removed	Photos
<b>Plant Room - Interior (Cont..)</b>														
78	<b>Western end of plant</b> Confined Space (inaccessible)	Not Determined	-	<b>Not Determined</b>  <i>Area Not Accessed</i>	-	-	-	-	-	Sep 2016	-	Investigate as soon as practicable and prior to any refurbishment/ demolition works by a suitably qualified occupational hygienist. Update the register accordingly.	Date: ___/___/___ Removed by: _____ Report: _____	<b>Photo 70</b> 
Comments: No assessed at time of inspection due to confined space.														<b>Not Determined</b>
<b>Adjacent Garage</b>														
79	<b>Interior</b> Throughout	Not Determined	-	<b>Not Determined</b>  <i>Area Not Accessed</i>	-	-	-	-	-	Sep 2016	-	Investigate as soon as practicable and prior to any refurbishment/ demolition works by a suitably qualified occupational hygienist. Update the register accordingly.	Date: ___/___/___ Removed by: _____ Report: _____	<b>Photo 71</b> 
Comments: No access available at the time of inspection.														<b>Not Determined</b>


## 8. Asbestos Management Plan

Asbestos materials were identified on the Site, please refer to Section 7 of the report for specific controls to be implemented with respect to each item identified.

Further to the measures outlined in Section 7, the controls of the Asbestos Management Plan (AMP) outlined in Sections 9 to 14 below are to be implemented by the personnel identified below in order for the effective ongoing control of the above asbestos containing materials located at the Site.

## 9. Hierarchy of Control

Ashfield Council are to ensure that a hierarchy of control is established between individuals identified within each level of control and those individuals made responsible for the effective implementation of the Asbestos Management Plan:





## 10. Responsibilities

### 10.1 Responsibilities of Ashfield Council

The following statements are the responsibility of the Owners of Ashfield Aquatic Centre, 160 Elizabeth Street, ASHFIELD NSW 2131 (i.e. Ashfield Council) in relation to the implementation and management of this AMP:

- Ensure a copy of the Asbestos Building Materials Register & Asbestos Management Plan for the Site is available to all site personnel, including maintenance workers (i.e. a current hard copy is stored in an easily accessible location and all workers are informed of its location).
- Ensure that these parties clearly understand the content and requirements of the AMP and ensure that compliance with the AMP is a condition of any legal agreement with these parties.
- Contractors undertaking friable asbestos related works must have a current Class A license and Contractors undertaking any other asbestos related works must have either a current Class A or Class B asbestos license.
- Engage an Occupational Hygienist to undertake a risk assessment of suspect material if concerns are raised regarding the condition of asbestos containing material or if there is a significant change in the condition of the asbestos containing material.
- Maintain records relating to the management of asbestos at the site.
- Update the AMP if The Owners become aware that Site conditions have changed and inform all relevant other parties of the changes; and
- Ensure that the minimum recommendations of this AMP and all legislative requirements are implemented on Site and ensure that where practicable or feasible any further recommended control or remediation measures recommended within this AMP are implemented.

### 10.2 Responsibilities of Maintenance Personnel & Tenants/Facility Managers

The following statements are the responsibility of Maintenance Personnel & Tenants/Store Managers in relation to the implementation and management of this AMP:

- Inform Ashfield Council if they become aware that Site conditions as they relate to asbestos containing materials have changed, and inform all relevant other parties of the changes.
- Comply with the AMP for all works undertaken, and

- Relay any inquiries relating to the management of asbestos contamination issues within Ashfield Aquatic Centre, 160 Elizabeth Street, ASHFIELD NSW 2131 to Ashfield Council.

### **10.3 Responsibilities of Contractors & Emergency Personnel Working On-Site**

The following statements are the responsibility of contractors and emergency personnel working on-site in relation to the implementation and management of this AMP:

- To ensure a Safe Work Permit document has been filled out before starting works.
- To ensure that work practices comply with those outlined with in this document and relevant Codes of Practice and legislation guidelines.
- Staff members employed have been suitably trained in the jobs that they are required to perform (including asbestos related work) and that they have been inducted to the Site.
- The Asbestos Building Materials Register & Asbestos Management Plan has been read and asbestos containing materials located physically on Site.
- Comply with the AMP for all works undertaken;
- Inform the relevant person controlling the works if conditions change significantly from those documented in the AMP; and
- Attend the Site in possession of the appropriate PPE as outlined in Section 13.


## 11. Consultation and Information

As per Section 4.3 of the Safe Work Australia Code of Practice (How to Manage & Control Asbestos in the Workplace), in the case of any works (including emergency works) taking place at asbestos affected areas, Ashfield Council are to ensure that all maintenance staff, tenants, contractors and emergency personnel undertaking work at asbestos affected areas have undergone an appropriate site specific induction in relation to the asbestos containing material that is present at the Site. The induction program is to be inclusive of the following:

- Information about asbestos containing material to which contractors/employees are or may be exposed to in the course of their work. Information is to include the nature of the hazard, identification of asbestos containing material and risks to health arising from exposure.
- Information about the locations of asbestos.
- Details of the asbestos containing material on site, including processes and safe work procedures to be followed to prevent exposure.
- Procedures to be followed in case of an emergency involving exposure of asbestos containing material.
- Incident reporting procedures to be followed in case of exposure or potential exposure of asbestos containing material.
- Personal protective equipment (PPE) requirements whilst working with asbestos.
- Records of all inductions must be kept for five years after the day the worker stops carrying out the **asbestos related work**. These records must also be available for inspection by the regulator (i.e. WorkCover NSW). Any contractor, maintenance staff, employee or other authorised persons who may potentially disturb the asbestos containing material on site must acknowledge within their Safe Work Method Statement and Risk Assessment the presence of asbestos within asbestos affected areas, must have signed onto a Permit to Work before commencing work and implement the appropriate controls as per Section 14.

## 12. Labelling

All Labels are to comply with Australian Standards AS1216 and AS1319. Examples of Labels are provided below:



The approximate dimensions of each label seen above will be as per follows:

- A: Height 72mm, Width 60mm;
- B: Height 67mm, Width at widest point 75mm;
- C: Height 76mm, Width 54mm;
- D: Height 67mm, Width at widest point 75mm;

Labeling in publicly sensitive areas is to be undertaken at the discretion of Ashfield Council.

Labeling is to be undertaken by a suitably trained and experienced Occupational Hygienist or competent person.

## 13. Steps Required During Asbestos Related Works

### 13.1 General Site Set Up

Prior to the commencement of asbestos related works the following procedures are to be observed:

- All friable asbestos related work is to be undertaken by a Class A licensed contractor.
- All bonded (non-friable) asbestos related work is to be undertaken by either a Class A or Class B licensed contractor.
- An exclusion zone from the work areas is to be established, barricaded and access restricted.
- A Permit to Work document has been filled out by all relevant parties.
- An appropriate Safe Work Method Statement and Risk Assessment are to be prepared by all parties involved and followed in accordance with site safety procedures. All personnel must read and sign each relevant document.
- Establish area for decontamination facilities (area for wetting down and disposal of PPE).
- All appropriate signage is to be erected, including appropriate asbestos warning signs.

### 13.2 General Requirements for Decontamination Works

During asbestos related works the following procedures are to be observed:

- All workers to wear appropriate Personal Protective Equipment (PPE), including respiratory protection (P2 or higher protection, P3 for friable asbestos related work), gloves, disposable overalls and safety shoes.
- Ensure all safety procedures are in place prior to starting work.
- At the completion of each work shift, use:
- Established area for decontamination facilities.
- Established area for wash down (decontamination) of equipment.
- All used PPE and waste generated is to be placed in 200µm thick plastic bags and disposed of as asbestos contaminated waste.

### 13.3 Painting or Cleaning of Asbestos Cement Sheeting

During painting or cleaning of asbestos cement sheeting the following procedures are to be observed as well as all steps with 14.1 and 14.2:

- The asbestos cement sheeting is to be inspected prior to commencing work to ensure that the sheets show no signs of deterioration or damage. If deterioration or damage is observed work must be stopped and emergency response procedures implemented.
- Drop sheets are to be installed within the work area to capture any dust generated and prevent the contamination of the ground/floor surfaces.
- Wet sanding may be used to prepare the surface before painting however the water must be captured and filtered prior to discharge. No dry sanding or high powered water cleaning methods are to be used during this task.
- When preparing the surface wet wiping may be used. During all wet wiping the rag must be not re-soaked and must be disposed of as asbestos waste after use.
- Apply paint gently using a roller or brush. High pressure spray methods are not to be used.

### 13.4 Drilling into Asbestos Cement Sheeting or Backing Boards

During drilling of asbestos cement sheeting works the following procedures are to be observed as well as all steps within 14.1 and 14.2:

- Drop sheets are to be installed below the drill area to capture any asbestos cement debris and prevent the contamination of the ground/floor surfaces.
- Apply tape to the front and back (if accessible) of the sheet. The tape used should be a heavy duty tape such as duct tape.
- Apply a generous amount of paste material to the drill and drill through surface.
- Use a non-powered hand drill or a low-speed battery-powered drill or drilling equipment fitted with a local exhaust ventilation (LEV) dust control hood. If a LEV is not available use the *shadow vacuuming technique* during the drilling process.
- All horizontal surfaces within the work area are to be vacuumed clean with a vacuum fitted with a HEPA filter until no visible signs of dust are present.
- All surfaces are to be wet wiped and the used rags disposed of as asbestos waste.
- A fine mist of PVA solution is to be applied to all surfaces following all drilling works.

### 13.5 Asbestos Air Monitoring & Clearance Inspection(s)

NATA accredited asbestos air monitoring is to be undertaken during all asbestos related works by a company such as Getex Pty Ltd.

If the results of the asbestos air monitoring during the asbestos related works indicate that airborne asbestos levels are equal to or exceed 0.02 fibres/mL, the Contractor shall cease work immediately, the work practice shall be reviewed with appropriate measures taken to rectify the problems.

- Following all asbestos related works an Occupational Hygienist from a company such as Getex Pty Ltd is to conduct a Clearance Assessment. The Clearance Assessment will involve:
  - A visual inspection to check if all visually identified asbestos containing material has been removed to a satisfactory industry standard.
  - The in situ asbestos containing material remaining onsite has been sealed to a satisfactory industry standard; and


In the case of Friable Asbestos Removal, Clearance Asbestos Air Monitoring will also be required.

- Subsequent to a satisfactory Clearance Assessment results an Asbestos Clearance Certificate will be issued.

## 14. Emergency Response

In the event of an uncontrolled disturbance of any asbestos containing material, the following procedures are to be observed:

- An exclusion zone from the contaminated area is to be established, barricaded and access restricted.
- All appropriate signage is to be erected surrounding the exclusion zone, including appropriate asbestos warning signs.
- Establish and utilise an area for decontamination facilities for wetting down and disposal of contaminated clothing (If required).
- An independent consultant competent in asbestos related contamination issues, such as Getex Pty Ltd, is to be contacted to facilitate asbestos management/removal activities.
- **The following Flow Chart should be utilised to safely and efficiently minimize any risk and return the Site to a safe condition for works to Proceed.**





## 15. Review of the Asbestos Management Plan

The Asbestos Management Plan is to be reviewed and, if necessary, revised at least once every five years or when:

- Asbestos is removed from or further disturbed on the site;
- The plan is no longer adequate for managing the asbestos containing material; or
- A health and safety representative requests a review if they reasonably believe that any of the matters listed in the above points affects or may affect the health and safety of a member of their work group.

The five year review is to be conducted by a suitably qualified occupational hygienist such as Getex. Reviews and amendments in the interim may be conducted by a suitably qualified Staff member.



# **APPENDIX I**

## **Sample Register & Laboratory Analysis Reports**



## SAMPLE REGISTER

Prepared by Getex

Sample No.	Material Type	Analysis Result	Building Reference	Area Reference	Location	Sample Location
9206.09/AS01	Fibre Cement Sheeting	No Asbestos Detected	Main Entrance Building	Exterior	Eastern side - Wall and carport - Upper panels	The sample of fibre cement sheeting was collected from the southern edge of the panels to the carport.
9206.09/AS02	Fibre Cement Sheeting	No Asbestos Detected	Main Entrance Building	Interior	Men's Change Room - Eastern non solid walls	The sample of fibre cement sheeting was collected from the northern end of the non solid walls.
9206.09/AS03	Vinyl Tile & Adhesive	No Asbestos Detected	Main Entrance Building	Office South of Entrance - Interior	North-western room - Eastern wall - Brown vinyl floor tiles and adhesive	The sample of vinyl tile and adhesive was collected from the south-eastern corner.
<b>9206.09/AS04</b>	<b>Seamless Vinyl</b>	<b>Chrysotile Asbestos Detected</b>	<b>Caretakers Cottage/Plant Room</b>	<b>Cottage - Interior</b>	<b>Kitchen - Floor - Seamless vinyl</b>	<b>The sample of seamless vinyl was collected from the south-eastern corner of the Kitchen.</b>
9206.09/AS05	Vinyl Tile	No Asbestos Detected	Caretakers Cottage/Plant Room	Cottage - Interior	Kitchen - Floor - Green vinyl tiles under seamless vinyl	The sample of vinyl tile was collected from the south-eastern corner of the Kitchen.
9206.09/AS06	Mastic	No Asbestos Detected	Caretakers Cottage/Plant Room	Cottage - Interior	Metal window frames - Throughout - Mastic	The sample of mastic was collected from the window within the room adjacent west of the southern entrance door.
9206.09/AS07	Fibre Cement Sheeting	No Asbestos Detected	Caretakers Cottage/Plant Room	Cottage - Interior	Southern entrance hall - Eastern wall	The sample of fibre cement sheeting was collected from the northern end of the wall.
9206.09/AS08	Mastic	No Asbestos Detected	Caretakers Cottage/Plant Room	Cottage - Exterior	Metal windows - Throughout - Mastic	The sample of mastic was collected from the window adjacent to the bottom of the northern stairs.
9206.09/AS09	Gasket	No Asbestos Detected	Caretakers Cottage/Plant Room	Plant Room - Interior	Main soil valve - Gasket	The sample of gasket was collected from the south-western corner of the gasket.



## SAMPLE REGISTER

Prepared by Getex

Sample No.	Material Type	Analysis Result	Building Reference	Area Reference	Location	Sample Location
9206.09/LP01	Paint	Lead in Paint <1.0%	Main Entrance Building	Exterior	Door frames and window frames - Throughout - White paint	The sample of white door frame paint was carried out on the western frame of the southern doorway to the room adjacent east of the Men's Change Room.
9206.09/LP02	Paint	Lead in Paint <1.0%	Main Entrance Building	Exterior	Southern side - Door adjacent west of western clock - Blue paint and multiple undercoats	The sample of blue door paint and multiple undercoats was collected centrally on the door.
9206.09/LP03	Paint	Lead in Paint <1.0%	Main Entrance Building	Office West of entrance - Interior	Walls throughout - Cream wall paint and undercoats	The sample of cream wall paint and undercoats was collected on the southern wall adjacent east of the window.
9206.09/LP04	Paint	Lead in Paint <1.0%	Main Entrance Building	Interior	First Aid Room - Walls - Blue paint and undercoats	The sample of blue wall paint and undercoats was collected from the southern wall adjacent west of the window.
9206.09/LP05	Paint	Lead in Paint <1.0%	Caretakers Cottage/Plant Room	Cottage - Interior	Walls throughout - Beige paint	The sample of beige wall paint was collected from the southern end of the eastern wall within the Kitchen.
9206.09/LP06	Paint	Lead in Paint <1.0%	Caretakers Cottage/Plant Room	Cottage - Interior	Laundry - Ceiling and upper timber trim - Cream paint	The sample of cream timber trim paint was collected centrally above the southern wall on the upper trim.
9206.09/LP07	Paint	Lead in Paint <1.0%	Caretakers Cottage/Plant Room	Plant Room - Interior	Walls throughout - Light green wall paint	The sample of light green wall paint was collected centrally on the southern wall.
9206.09/LPST01	Paint	Lead in Paint <1.0%	Main Entrance Building	Exterior	Walls - Throughout - White paint	The spot test of white wall paint was carried out on the southern end of the eastern exterior wall to the office adjacent south of the entrance.
9206.09/LPST02	Paint	Lead in Paint <1.0%	Main Entrance Building	Exterior	Walls - Throughout - Blue paint trim	The spot test of blue paint trim was carried out on the southern end of the eastern exterior wall to the office adjacent south of the entrance.



## SAMPLE REGISTER

Prepared by Getex

Sample No.	Material Type	Analysis Result	Building Reference	Area Reference	Location	Sample Location
9206.09/LPST03	Paint	Lead in Paint <1.0%	Main Entrance Building	Interior	Walls throughout - White paint	The spot test of white wall paint was carried out adjacent east of the window on the southern wall within room adjacent south of the Club Room.
9206.09/LPST04	Paint	Lead in Paint <1.0%	Main Entrance Building	Office South of Entrance - Interior	Walls throughout - Blue paint	The spot test of blue wall paint was carried out on the northern wall adjacent south of the entrance door.
9206.09/LPST05	Paint	Lead in Paint <1.0%	Main Entrance Building	Office South of Entrance - Interior	Door and door frames - Blue paint	The spot test of blue door paint was carried out on the southern edge of the exterior side of the entrance door.
<b>9206.09/LPST06</b>	<b>Paint</b>	<b>Lead in Paint &gt;1.0%</b>	<b>Main Entrance Building</b>	<b>Interior</b>	<b>First Aid Room - Walls - Adjacent change room - Walls - Beige paint</b>	<b>The spot test of beige wall paint was carried out on the northern wall adjacent east of the pipe.</b>
<b>9206.09/LPST07</b>	<b>Paint</b>	<b>Lead in Paint &gt;1.0%</b>	<b>Main Entrance Building</b>	<b>Interior</b>	<b>Male Staff Change Room - Walls - Yellow paint</b>	<b>The spot test of yellow wall paint was carried out centrally on the northern wall.</b>
9206.09/LPST08	Paint	Lead in Paint <1.0%	Main Entrance Building	Kiosk - Interior	Kitchen area - Walls - White paint	The spot test of white wall paint was carried out in the western section of the Kitchen adjacent south of the western doorway.
9206.09/LPST09	Paint	Lead in Paint <1.0%	Main Entrance Building	Kiosk - Interior	Shop area - Walls - Maroon paint	The spot test of maroon wall paint was carried out on the northern wall adjacent west of the western doorway.
9206.09/LPST10	Paint	Lead in Paint <1.0%	Pool Area	Exterior	Walls - Throughout - Purple paint	The spot test of purple paint was carried out on the western end of the wall adjacent east of the Kiosk.
9206.09/LPST11	Paint	Lead in Paint <1.0%	Pool Area	Exterior	Outdoor pools - Blue paint trim	The spot test of blue paint trim was carried out on the northern end of the eastern side of the eastern pool.



## SAMPLE REGISTER

Prepared by Getex

Sample No.	Material Type	Analysis Result	Building Reference	Area Reference	Location	Sample Location
9206.09/LPST12	Paint	Lead in Paint <1.0%	Pool Area	Grandstands	Walls and floor - White paint and grey undercoat	The spot test of white wall paint with grey undercoat was carried out on the exterior north-eastern corner of the western grandstand.
9206.09/LPST13	Paint	Lead in Paint <1.0%	Main Entrance Building	Exterior	Non timber panel doors - Throughout - Blue paint	The spot test of blue door paint was carried out on the southern entrance door to the room adjacent south of the Club Room.
9206.09/LPST14	Paint	Lead in Paint <1.0%	Caretakers Cottage/Plant Room	Cottage - Interior	Walls throughout - Green paint	The spot test of green wall paint was carried out on the eastern wall adjacent north of the entrance to the Kitchen within the Living Room.
<b>9206.09/LPST15</b>	<b>Paint</b>	<b>Lead in Paint &gt;1.0%</b>	<b>Caretakers Cottage/Plant Room</b>	<b>Cottage - Interior</b>	<b>Laundry - Walls - Yellow paint</b>	<b>The spot test of yellow wall paint was carried out on the southern end of the southern wall.</b>
9206.09/LPST16	Paint	Lead in Paint <1.0%	Caretakers Cottage/Plant Room	Plant Room - Interior	Ceiling and upper beams - White paint	The spot test of white beam paint was carried out centrally on the central ceiling beam.
9206.09/LPST18	Paint	Lead in Paint <1.0%	Main Entrance Building	Exterior	Northern Side - Kiosk carport - Eaves and ceiling - White paint	The spot test of white eaves paint was carried out on the eaves located 1 metre from the north-eastern corner of the building.



## ASBESTOS SAMPLE ANALYSIS REPORT

**Report Number:** 9206.09.ANAT  
**Report Date:** 5 November 2015

### 1. CLIENT DETAILS

**Client Company:** Ashfield Council  
**Client Contact:** Ray McMaster  
**Client Address:** 260 Liverpool Road  
ASHFIELD NSW 2131

**Date Samples Received:** 1 October 2015

### 2. SCOPE

GETEX PTY LTD was requested by Ray McMaster of Ashfield Council to analyse nine (9) samples for asbestos content. The analysis results only relate to the samples tested.

### 3. METHOD

The samples were analysed under a Stereomicroscope and selected fibres were analysed by Polarised Light Microscopy in conjunction with dispersion staining method (GETEX.BSA.01, NATA accreditation number 15404). This method is based on the AS 4964-2004 Method for the qualitative identification of asbestos in bulk samples.



NATA Accredited Laboratory.  
Number: 15404

The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.

Accredited for compliance with ISO/IEC 17025

This report shall not be reproduced except in full.

**GETEX PTY LIMITED**  
ABN 99 116 287 471

Suite 2.02, Level 2, Waterloo Business Park  
35 Waterloo Road, Macquarie Park NSW 2113  
Phone: (02) 98892488 Fax: (02) 98892499  
Email: help@getex.com.au Web: www.getex.com.au

#### 4. RESULTS

Sample Number	Description	Analysis Result
9206.09/AS01	Approximate dimensions 11mm x 8mm x 5mm. The sample consisted of a fragment of fibre cement material containing organic fibres.	No Asbestos Detected
9206.09/AS02	Approximate dimensions 10mm x 7mm x 2.5mm. The sample consisted of a fragment of fibre cement material containing organic fibres.	No Asbestos Detected
9206.09/AS03	Approximate dimensions 37mm x 14mm x 2.3mm. The sample consisted of a fragment of brown vinyl material containing organic fibres with adhesive on one side.	No Asbestos Detected
9206.09/AS04	Approximate dimensions 56mm x 19mm x 1mm. The sample consisted of a fragment of brown patterned vinyl material with felt* like backing material containing organic fibres.	<b>*Chrysotile Asbestos Detected</b>
9206.09/AS05	Approximate dimensions 33mm x 22mm x 3.4mm. The sample consisted of a fragment of green vinyl material with hessian and felt like backing material containing organic fibres.	No Asbestos Detected
9206.09/AS06	Approximate dimensions 20mm x 7mm x 1.9mm. The sample consisted of a fragment of sealant material.	No Asbestos Detected
9206.09/AS07	Approximate dimensions 15mm x 8mm x 2.7mm. The sample consisted of a fragment of fibre cement material containing organic fibres.	No Asbestos Detected
9206.09/AS08	Approximate dimensions 15mm x 14mm x 7mm. The sample consisted of a fragment of sealant material.	No Asbestos Detected



NATA Accredited Laboratory.  
Number:15404

The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.

Accredited for compliance with ISO/IEC 17025

This report shall not be reproduced except in full.

9206ash09-ANAT

GETEX



Sample Number	Description	Analysis Result
9206.09/AS09	Approximate dimensions 7mm x 5mm x 3.2mm. The sample consisted of a fragment of fibre board material containing organic fibres.	No Asbestos Detected

## 5. LIMITATIONS

Although all work is performed to a professional and diligent standard, the potential variance between the practical limitations of the scope of work undertaken, the cost of our services, all possible issues of concern, and any loss or damages which may be associated with our work are such that we cannot warrant that all asbestos materials have been identified. We therefore limit any potential liability associated with our work to the cost of our services. Furthermore there can be no guarantee that a particular sample is typical of an extended area.

Kind Regards,



Geronimo Abrot BScMEng  
Approved Identifier

QA/QC check by:



Lee Hands BSc Hons  
Approved Signatory



NATA Accredited Laboratory.  
Number:15404

The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards.

Accredited for compliance with ISO/IEC 17025

This report shall not be reproduced except in full.

9206ash09-ANAT

GETEX



12 Ashley Street, Chatswood, NSW 2067  
tel: +61 2 9910 6200

email: [sydney@envirolab.com.au](mailto:sydney@envirolab.com.au)  
[envirolab.com.au](http://envirolab.com.au)

Envirolab Services Pty Ltd - Sydney | ABN 37 112 535 645

**CERTIFICATE OF ANALYSIS**

**135413**

**Client:**

**Getex Pty Ltd**  
2.02, Building 2 Waterloo Business Park  
35 Waterloo Rd  
North Ryde  
NSW 2113

**Attention:** Peter Fox

**Sample log in details:**

Your Reference: **9206**  
No. of samples: 37 Paints, 18 Swabs  
Date samples received / completed instructions received 06/10/15 / 06/10/15

**Analysis Details:**

Please refer to the following pages for results, methodology summary and quality control data.  
Samples were analysed as received from the client. Results relate specifically to the samples as received.  
Results are reported on a dry weight basis for solids and on an as received basis for other matrices.  
***Please refer to the last page of this report for any comments relating to the results.***

**Report Details:**

Date results requested by: / Issue Date: 13/10/15 / 13/10/15  
Date of Preliminary Report: Not Issued  
NATA accreditation number 2901. This document shall not be reproduced except in full.  
Accredited for compliance with ISO/IEC 17025. **Tests not covered by NATA are denoted with \*.**

**Results Approved By:**

  
\_\_\_\_\_  
Jacinta Hurst  
Laboratory Manager

Envirolab Reference: 135413  
Revision No: R 00



Client Reference: 9206

Lead in Paint Our Reference: Your Reference Type of sample	UNITS ----- -----	135413-1 9206.03/LP01 Paint	135413-2 9206.03/LP02 Paint	135413-3 9206.03/LP03 Paint	135413-4 9206.03/LP04 Paint	135413-5 9206.03/LP05 Paint
Date prepared	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Date analysed	-	12/10/2015	12/10/2015	12/10/2015	12/10/2015	12/10/2015
Lead in paint	% w/w	7.8	<0.05	2.8	0.96	4.6

Lead in Paint Our Reference: Your Reference Type of sample	UNITS ----- -----	135413-6 9206.03/LP06 Paint	135413-8 9206.04/LP01 Paint	135413-9 9206.04/LP02 Paint	135413-10 9206.04/LP03 Paint	135413-11 9206.04/LP04 Paint
Date prepared	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Date analysed	-	12/10/2015	12/10/2015	12/10/2015	12/10/2015	12/10/2015
Lead in paint	% w/w	<0.05	11	3.7	4.5	1.2

Lead in Paint Our Reference: Your Reference Type of sample	UNITS ----- -----	135413-15 9206.05/LP01 Paint	135413-16 9206.05/LP02 Paint	135413-17 9206.05/LP03 Paint	135413-18 9206.05/LP04 Paint	135413-21 9206.09/LP01 Paint
Date prepared	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Date analysed	-	12/10/2015	12/10/2015	12/10/2015	12/10/2015	12/10/2015
Lead in paint	% w/w	14	4.0	1.5	0.3	0.2

Lead in Paint Our Reference: Your Reference Type of sample	UNITS ----- -----	135413-22 9206.09/LP02 Paint	135413-23 9206.09/LP03 Paint	135413-24 9206.09/LP04 Paint	135413-25 9206.09/LP05 Paint	135413-26 9206.09/LP06 Paint
Date prepared	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Date analysed	-	12/10/2015	12/10/2015	12/10/2015	12/10/2015	12/10/2015
Lead in paint	% w/w	0.98	0.1	0.07	0.1	0.1

Lead in Paint Our Reference: Your Reference Type of sample	UNITS ----- -----	135413-27 9206.09/LP07 Paint	135413-28 9206.10- 1/LP01 Paint	135413-29 9206.10- 1/LP02 Paint	135413-32 9206.12/LP01 Paint	135413-33 9206.12/LP02 Paint
Date prepared	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Date analysed	-	12/10/2015	12/10/2015	12/10/2015	12/10/2015	12/10/2015
Lead in paint	% w/w	0.08	13	0.3	0.2	1.3

Lead in Paint Our Reference: Your Reference Type of sample	UNITS ----- -----	135413-34 9206.12/LP03 Paint	135413-35 9206.12/LP04 Paint	135413-37 9206.13/LP01 Paint	135413-38 9206.13/LP02 Paint	135413-39 9206.14/LP01 Paint
Date prepared	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Date analysed	-	12/10/2015	12/10/2015	12/10/2015	12/10/2015	12/10/2015
Lead in paint	% w/w	0.50	0.08	0.09	0.1	0.1

**Client Reference: 9206**

Lead in Paint Our Reference: Your Reference Type of sample	UNITS ----- -----	135413-41 9206.16/LP01 Paint	135413-42 9206.16/LP02 Paint	135413-46 9206.18/LP01 Paint	135413-48 9206.20/LP01 Paint	135413-53 9206.24/LP01 Paint
Date prepared	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Date analysed	-	12/10/2015	12/10/2015	12/10/2015	12/10/2015	12/10/2015
Lead in paint	% w/w	<0.05	5.5	0.2	0.08	10

Lead in Paint Our Reference: Your Reference Type of sample	UNITS ----- -----	135413-54 9206.24/LP02 Paint	135413-55 9206.24/LP03 Paint	135413-56 9206.09/LP02 - TRIPLICATE Paint
Date prepared	-	08/10/2015	08/10/2015	08/10/2015
Date analysed	-	12/10/2015	12/10/2015	12/10/2015
Lead in paint	% w/w	3.1	<0.05	<0.05

Envirolab Reference: 135413  
Revision No: R 00

Client Reference: 9206

Lead in swab Our Reference: Your Reference Type of sample	UNITS ----- -----	135413-7 9206.03/LD01 Swab	135413-12 9206.04/LD01 Swab	135413-13 9206.04/LD02 Swab	135413-14 9206.04/LD03 Swab	135413-19 9206.07/LD01 Swab
Date prepared	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Date analysed	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Lead in Swabs	µg/swab	87	590	13,000	26	10

Lead in swab Our Reference: Your Reference Type of sample	UNITS ----- -----	135413-20 9206.08/LD01 Swab	135413-30 9206.10- 2/LD01 Swab	135413-31 9206.10- 2/LD02 Swab	135413-36 9206.12/LD01 Swab	135413-40 9206.14/LD01 Swab
Date prepared	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Date analysed	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Lead in Swabs	µg/swab	15	68	4	4,100	88

Lead in swab Our Reference: Your Reference Type of sample	UNITS ----- -----	135413-43 9206.16/LD01 Swab	135413-44 9206.16/LD02 Swab	135413-45 9206.17/LD01 Swab	135413-47 9206.19/LD01 Swab	135413-49 9206.20/LD01 Swab
Date prepared	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Date analysed	-	08/10/2015	08/10/2015	08/10/2015	08/10/2015	08/10/2015
Lead in Swabs	µg/swab	30	370	13	220	160

Lead in swab Our Reference: Your Reference Type of sample	UNITS ----- -----	135413-50 9206.20/LD02 Swab	135413-51 9206.23/LD01 Swab	135413-52 9206.23/LD02 Swab
Date prepared	-	08/10/2015	08/10/2015	08/10/2015
Date analysed	-	08/10/2015	08/10/2015	08/10/2015
Lead in Swabs	µg/swab	290	270	74

**Client Reference: 9206**

MethodID	Methodology Summary
Metals-004	Digestion of Paint chips/scrapings/liquids for Metals determination by ICP-AES/MS and or CV/AAS.
Metals-005	Digestion of Dust wipes/swabs and /or miscellaneous samples for Metals determination by ICP-AES/MS and/or CV-AAS

Envirolab Reference: 135413  
Revision No: R 00

Page 5 of 8

Client Reference: 9206

QUALITY CONTROL	UNITS	PQL	METHOD	Blank	Duplicate Sm#	Duplicate results	Spike Sm#	Spike % Recovery
Lead in Paint						Base    Duplicate    %RPD		
Date prepared	-			08/10/2015	135413-2	08/10/2015    08/10/2015	LCS-1	08/10/2015
Date analysed	-			12/10/2015	135413-2	12/10/2015    12/10/2015	LCS-1	12/10/2015
Lead in paint	% w/w	0.05	Metals-004	<0.05	135413-2	<0.05    <0.05	LCS-1	107%
QUALITY CONTROL	UNITS	PQL	METHOD	Blank	Duplicate Sm#	Duplicate results	Spike Sm#	Spike % Recovery
Lead in swab						Base    Duplicate    %RPD		
Date prepared	-			08/10/2015	[NT]	[NT]	LCS-1	08/10/2015
Date analysed	-			08/10/2015	[NT]	[NT]	LCS-1	08/10/2015
Lead in Swabs	µg/swab	1	Metals-005	<1	[NT]	[NT]	LCS-1	102%
QUALITY CONTROL	UNITS	Dup. Sm#	Duplicate	Spike Sm#	Spike % Recovery			
Lead in Paint			Base + Duplicate + %RPD					
Date prepared	-	135413-15	08/10/2015    08/10/2015	LCS-2	08/10/2015			
Date analysed	-	135413-15	12/10/2015    12/10/2015	LCS-2	12/10/2015			
Lead in paint	% w/w	135413-15	14    17    RPD: 19	LCS-2	105%			
QUALITY CONTROL	UNITS	Dup. Sm#	Duplicate	Spike Sm#	Spike % Recovery			
Lead in Paint			Base + Duplicate + %RPD					
Date prepared	-	135413-22	08/10/2015    08/10/2015	LCS-3	08/10/2015			
Date analysed	-	135413-22	12/10/2015    12/10/2015	LCS-3	12/10/2015			
Lead in paint	% w/w	135413-22	0.98    0.5    RPD: 65	LCS-3	105%			
QUALITY CONTROL	UNITS	Dup. Sm#	Duplicate					
Lead in Paint			Base + Duplicate + %RPD					
Date prepared	-	135413-26	08/10/2015    08/10/2015					
Date analysed	-	135413-26	12/10/2015    12/10/2015					
Lead in paint	% w/w	135413-26	0.1    0.1    RPD: 0					
QUALITY CONTROL	UNITS	Dup. Sm#	Duplicate					
Lead in Paint			Base + Duplicate + %RPD					
Date prepared	-	135413-46	08/10/2015    08/10/2015					
Date analysed	-	135413-46	12/10/2015    12/10/2015					
Lead in paint	% w/w	135413-46	0.2    0.2    RPD: 0					
QUALITY CONTROL	UNITS	Dup. Sm#	Duplicate					
Lead in Paint			Base + Duplicate + %RPD					
Date prepared	-	135413-53	08/10/2015    08/10/2015					
Date analysed	-	135413-53	12/10/2015    12/10/2015					
Lead in paint	% w/w	135413-53	10    9.9    RPD: 1					

Envirolab Reference: 135413  
Revision No: R 00

**Client Reference: 9206**

**Report Comments:**

Acid Extractable Metals in Soil: The laboratory RPD acceptance criteria has been exceeded for 135413-22 for Pb. Therefore a triplicate result has been issued as laboratory sample number 135413-56.

Acid Extractable Metals in Paint: Sample 22; paint is bonded to substrate, every effort has been made to scrape the paint off.

Asbestos ID was analysed by Approved Identifier: Not applicable for this job  
Asbestos ID was authorised by Approved Signatory: Not applicable for this job

INS: Insufficient sample for this test  
NA: Test not required  
<: Less than

PQL: Practical Quantitation Limit  
RPD: Relative Percent Difference  
>: Greater than

NT: Not tested  
NA: Test not required  
LCS: Laboratory Control Sample

Envirolab Reference: 135413  
Revision No: R 00

Page 7 of 8



**Quality Control Definitions**

**Blank:** This is the component of the analytical signal which is not derived from the sample but from reagents, glassware etc, can be determined by processing solvents and reagents in exactly the same manner as for samples.

**Duplicate:** This is the complete duplicate analysis of a sample from the process batch. If possible, the sample selected should be one where the analyte concentration is easily measurable.

**Matrix Spike :** A portion of the sample is spiked with a known concentration of target analyte. The purpose of the matrix spike is to monitor the performance of the analytical method used and to determine whether matrix interferences exist.

**LCS (Laboratory Control Sample) :** This comprises either a standard reference material or a control matrix (such as a blank sand or water) fortified with analytes representative of the analyte class. It is simply a check sample.

**Surrogate Spike:** Surrogates are known additions to each sample, blank, matrix spike and LCS in a batch, of compounds which are similar to the analyte of interest, however are not expected to be found in real samples.

**Laboratory Acceptance Criteria**

Duplicate sample and matrix spike recoveries may not be reported on smaller jobs, however, were analysed at a frequency to meet or exceed NEPM requirements. All samples are tested in batches of 20. The duplicate sample RPD and matrix spike recoveries for the batch were within the laboratory acceptance criteria.

Filters, swabs, wipes, tubes and badges will not have duplicate data as the whole sample is generally extracted during sample extraction.

Spikes for Physical and Aggregate Tests are not applicable.

For VOCs in water samples, three vials are required for duplicate or spike analysis.

Duplicates: <5xPQL - any RPD is acceptable; >5xPQL - 0-50% RPD is acceptable.

Matrix Spikes, LCS and Surrogate recoveries: Generally 70-130% for inorganics/metals; 60-140% for organics (+/-50% surrogates) and 10-140% for labile SVOCs (including labile surrogates), ultra trace organics and speciated phenols is acceptable.

In circumstances where no duplicate and/or sample spike has been reported at 1 in 10 and/or 1 in 20 samples respectively, the sample volume submitted was insufficient in order to satisfy laboratory QA/QC protocols.

When samples are received where certain analytes are outside of recommended technical holding times (THTs), the analysis has proceeded. Where analytes are on the verge of breaching THTs, every effort will be made to analyse within the THT or as soon as practicable.



**Envirolab Services Pty Ltd**  
 ABN 37 112 535 645  
 12 Ashley St Chatswood NSW 2067  
 ph 02 9910 6200 fax 02 9910 6201  
 enquiries@envirolabservices.com.au  
 www.envirolabservices.com.au

### SAMPLE RECEIPT ADVICE

Client Details	
Client	Getex Pty Ltd
Attention	Peter Fox

Sample Login Details	
Your Reference	9206
Envirolab Reference	135413
Date Sample Received	06/10/2015
Date Instructions Received	06/10/2015
Date Results Expected to be Reported	13/10/2015

Sample Condition	
Samples received in appropriate condition for analysis	YES
No. of Samples Provided	37 Paints, 18 Swabs
Turnaround Time Requested	Standard
Temperature on receipt (°C)	NA
Cooling Method	Not applicable
Sampling Date Provided	Not Provided on the COC

Comments
Samples will be held for 1 month for water samples and 2 months for soil samples from date of receipt of samples

Please direct any queries to:

Aileen Hie	Jacinta Hurst
Phone: 02 9910 6200	Phone: 02 9910 6200
Fax: 02 9910 6201	Fax: 02 9910 6201
Email: ahie@envirolabservices.com.au	Email: jhurst@envirolabservices.com.au

Sample and Testing Details on following page

<i>Sample Id</i>	<i>Lead in Paint</i>	<i>Lead in swab</i>
9206.03/LP01	✓	
9206.03/LP02	✓	
9206.03/LP03	✓	
9206.03/LP04	✓	
9206.03/LP05	✓	
9206.03/LP06	✓	
9206.03/LD01		✓
9206.04/LP01	✓	
9206.04/LP02	✓	
9206.04/LP03	✓	
9206.04/LP04	✓	
9206.04/LD01		✓
9206.04/LD02		✓
9206.04/LD03		✓
9206.05/LP01	✓	
9206.05/LP02	✓	
9206.05/LP03	✓	
9206.05/LP04	✓	
9206.07/LD01		✓
9206.08/LD01		✓
9206.09/LP01	✓	
9206.09/LP02	✓	
9206.09/LP03	✓	
9206.09/LP04	✓	
9206.09/LP05	✓	
9206.09/LP06	✓	
9206.09/LP07	✓	
9206.10-1/LP01	✓	
9206.10-1/LP02	✓	
9206.10-2/LD01		✓
9206.10-2/LD02		✓
9206.12/LP01	✓	
9206.12/LP02	✓	
9206.12/LP03	✓	
9206.12/LP04	✓	
9206.12/LD01		✓
9206.13/LP01	✓	
9206.13/LP02	✓	
9206.14/LP01	✓	
9206.14/LD01		✓
9206.16/LP01	✓	
9206.16/LP02	✓	
9206.16/LD01		✓
9206.16/LD02		✓
9206.17/LD01		✓
9206.18/LP01	✓	



**Envirolab Services Pty Ltd**  
ABN 37 112 535 645  
12 Ashley St Chatswood NSW 2067  
ph 02 9910 6200 fax 02 9910 6201  
enquiries@envirolabservices.com.au  
www.envirolabservices.com.au

9206.19/LD01		✓
9206.20/LP01	✓	
9206.20/LD01		✓
9206.20/LD02		✓
9206.23/LD01		✓
9206.23/LD02		✓
9206.24/LP01	✓	
9206.24/LP02	✓	
9206.24/LP03	✓	



From: Getex Pty Ltd  
 Address: 2.02, Building 2, Waterloo Business Park  
 35 Waterloo Road  
 North Ryde NSW 2113  
 Phone: (02) 9889 2488  
 Facsimile: (02) 9889 2499  
 Email: help@getex.com.au  
 Attention: Peter Fox

**CHAIN OF CUSTODY FORM**

To: Envirolab Services Pty Ltd  
 Address: 12 Ashley  
 Chatswood NSW 2067  
 Phone: (02) 9910 6200  
 Facsimile: (02) 9958 5803

Date: 2/10/2015  
 Order No.: 5384  
 Project No.: 9206

TAT Required: **5 Day TAT**

Standard Water Detection Limits (ANZECC 2000 95%)  Special Water Detection Limits  
 (Please advise of additional charges)

Samples received at ambient temperature  Samples received chilled Received by (signature) CALUM CB. Date: 6.10.15.

Envirolab Barcode Number	GETEX Sample Number	Container Plastic Tube – PT Bag – B Petri Dish – PD Plastic Bottle – PB Glass Jar – GJ Glass Bottle – GB Glass Vial – GV	Soil							DDG Content							Paint/Dust Filters/Wipes							
			TPH/BTEX	Metals <sup>1</sup>	PAH	OC/OP/PCB	VOC	Leachate Metals <sup>2</sup> (mg/L)	Leachate PAH (mg/L)	Other	Ash & Comb. Matter	Total Soluble Matter	Total Insoluble Matter	Total Solids					Other	Lead (mg/kg)	Lead Total (mg)	Other		
135413. 1	9206.03/LP01	PT																			X			
2	9206.03/LP02	PT																				X		
3	9206.03/LP03	PT																				X		
4	9206.03/LP04	PT																				X		
5	9206.03/LP05	PT																				X		
6	9206.03/LP06	PT																				X		
7	9206.03/LD01	PT																					X	
8	9206.04/LP01	PT																				X		
9	9206.04/LP02	PT																				X		
10	9206.04/LP03	PT																				X		
11	9206.04/LP04	PT																				X		
12	9206.04/LD01	PT																					X	
13	9206.04/LD02	PT																					X	
14	9206.04/LD03	PT																					X	
15	9206.05/LP01	PT																				X		

Envirolab Services  
 12 Ashley St  
 Chatswood NSW 2067  
 Ph: (02) 9910 6200  
 Job No: 135413  
 Date Received: 6.10.15.  
 Time Received: 9.30.  
 Received by: CB.  
 Temp: Cool/Ambient  
 Coding: Ice/Leakpack  
 Security: Intact/Broken/None

9206env01-COC  
 GETEX Form.Lab.016 (Edition 1; 7 November 2005)



