

Hoskins Park Upgrade

Concept Plan



Legend

- Indicative extent of works
- Contours (0.2m intervals)
- Concrete surface
- Rubber softfall surface
- Mulch softfall surface
- Turf
- Native planting
- Proposed native tree
- Existing tree retained

Key

Park Upgrades

- 1 Existing entry posts, pergola & name plaque restored
- 2 Existing pathway retained & protected
- 3 Existing pathway & kerbs upgraded
- 4 Existing bench seat retained
- 5 Existing drinking fountain retained
- 6 New handrail to existing stairs
- 7 New accessible path to playground
- 8 New picnic setting
- 9 New BBQ
- 10 Relocated bench seat
- 11 New native planting
- 12 Relocated bin stand

Key

Playground Upgrades

- a** New embankment slide (2+ years)
- b** New toddler play mound with slide & rope climb (2+ years)
- c** New in-ground trampoline
- d** New multi play unit (6+ years)
- e** New seats to existing swing set
- f** New nature play area with natural materials using repurposed playground equipment
- g** New flush concrete edge
- h** New shade sail to toddler play area
- i** Existing concrete retained



Upgraded pathways



Upgraded playground - mounds, climbing & slides



Upgraded playground - multi-play unit



Picnic & BBQ area